



M.J. Hickey Plant Hire Ltd

Unit 11, Bristol Way Slough Berkshire SL1 3TD

T: 01753 651 202 E: accounts@hickeyplanthire.co.uk W: www.hickeyplanthire.co.uk

VAT Reg. No. 480 0958 39

Morrison Galliford JV
PO Box 7440
Hinckley
Leicestershire
LE10 1YL

INVOICE

Page 1

Invoice No	49277
Invoice Date	30/06/2026
Order No	9400016708P
Account Ref	MGJV

Description

Net Amt

VAT %

VAT



Supply 14t Duck Self drive

Dates: 01/06/2026 - 30/06/2026

14t Duck working time

4.4 weeks @ £800 per week

3,520.00 20.00 704.00

Tyre Repair

Inv - 77284634 - £233.50

Inv - 77284870 - £526.00

759.50 20.00 151.90

Site Address

Yew Hill Reservoir

Hire continues

Total Net Amount	£	4,279.50
Total Tax Amount	£	855.90
Invoice Total	£	5,135.40

Please note our new bank details for all payments
Sort code: 536158 Account number: 71650776



Tyrefix Plant Tyres (UK) Ltd
Spring Road
Ibstock
Leicestershire
LE67 6LR

Fax: 01530 245786

Accounts: 01530 244444 Opt3

HOT LINE: 01530 244444

Bank: SEB London Sort Code: 40-48-65
A/C Name: Tyrefix Plant Tyres (UK) Ltd
A/C Number: 65297005

INVOICE

BILLING ADDRESS

M.J.HICKEY (PLANT HIRE) LTD
10 WOOD LANE CLOSE
IVER HEATH
BUCKS

SL0 0LJ

VEHICLE

RDUCK

REG/FLEET NO.

RDUCK

SPEEDO/HRS

7647

FITTING ADDRESS (IF DIFFERENT)

3RD/SPEC/WINCHESTER Four Dells
C/o Mgjv, Otterbourne
Spec/winchester
Hampshire
SO21 2DY

CALLED IN

ON SITE

COMPLETED

VAN ID

734

FITTER

734 - GARY BARBER

ADVICE NO.

JC294826

INVOICE NO.

77284634


ORDER NO.

ACCOUNT NO.

H569

DATE

12/06/26



JOB CARD

Pos	Tyre Size	Tread Depths			Ply	PSI		Brand	Condition	Service able	Disposal	Comment
		Centre	Mid	Outer		BF	AF					
B1	10.00-20	13	16	20	16	1.0	100.0	SUPREME	Average	Y	N	Repair Internal. Reason: Hole. Damage Size: 1mm
B2	10.00-20	13	18	27	16	13.0	100.0	ALLIANCE	Average	Y	N	Repair Internal. Reason: Hole. Damage Size: 1mm

TYRES REMOVED

APPROVED by DH

to Charge on

SIGNEE NAME: *C.MAOILED.DONE.Micheal

SIGNED: 

SITE CONDITION: Good

INVOICE

DESCRIPTION	QTY	PRICE	VALUE
URGENT - SPECIALIST REPAIR CIB: WILL , 07879671965 Site Contact: MICHAEL , 07446988887 Customer portal advised ETA of: 12/06/2026 12:15 1X SPEC REPAIR POSITION REAR LEFT OUTTER (B1) Vehicle Type: 6 1 X SUB REPAIR. SPECIALIST SUB This invoice refers to Advice Note JC294826	1	145.50	145.50
	1	88.00	88.00

RATE	AMOUNT TAXABLE	VAT TOTAL	TOTAL GOODS	TOTAL VAT	INVOICE TOTAL
20%	233.50	46.70	233.50	46.70	280.20

Tyrefix Plant Tyres (UK) Ltd
Spring Road
Ibstock
Leicestershire
LE67 6LR


INVOICE

Accounts: 01530 244444 Opt 2
Fax: 01530 245786
HOT LINE: 01530 244444


VEHICLE	FLEET NO.	JOB/ADVICE NO.	INVOICE NO.	ORDER NO.	DATE	ACC NO.	VAN RUN
RDUCK	RDUCK	JC294826	77284634		12/06/26	H569	14



Arrived on Site



Exclusion Zone




PPE




Vehicle Image - Reg/Fleet Num



Wheel Position: B1 - Tread Before



Wheel Position: B1 - Sidewall Before



Wheel Position: B1 - Wheel Nut Before



Wheel Position: B1 - Repair Reason



Wheel Position: B1 - Repair Material

Tyrefix Plant Tyres (UK) Ltd
Spring Road
Ibstock
Leicestershire
LE67 6LR

INVOICE

Accounts: 01530 244444 Opt 2
Fax: 01530 245786
HOT LINE: 01530 244444

VEHICLE	FLEET NO.	JOB/ADVICE NO.	INVOICE NO.	ORDER NO.	DATE	ACC NO.	VAN RUN
RDUCK	RDUCK	JC294826	77284634		12/06/26	H569	14




Wheel Position: B1 - Tread Depth Gauge




Wheel Position: B2 - Tread Before




Wheel Position: B2 - Sidewall Before




Wheel Position: B2 - Wheel Nut Before




Wheel Position: B2 - Tread Depth Gauge




Wheel Position: B2 - Torque Wheel Before



Wheel Position: B1 - Torque Wheel Before



Wheel Position: B1 - Repair Reason




Wheel Position: B1 - Repair Material

Tyrefix Plant Tyres (UK) Ltd
Spring Road
Ibstock
Leicestershire
LE67 6LR

INVOICE

Accounts: 01530 244444 Opt 2
Fax: 01530 245786
HOT LINE: 01530 244444


VEHICLE	FLEET NO.	JOB/ADVICE NO.	INVOICE NO.	ORDER NO.	DATE	ACC NO.	VAN RUN
RDUCK	RDUCK	JC294826	77284634		12/06/26	H569	14



Wheel Position: B2 - Repair Reason



Wheel Position: B2 - Repair Material



Wheel Position: B2 - Damage Size



Wheel Position: B2 - Torque 600.0 Nm



Wheel Position: B2 - Torque Tag



Wheel Position: B2 - Torque Wheel After



Wheel Position: B2 - Completed Repair



Wheel Position: B2 - Tread After




Wheel Position: B2 - Sidewall After

Tyrefix Plant Tyres (UK) Ltd
Spring Road
Ibstock
Leicestershire
LE67 6LR

INVOICE

Accounts: 01530 244444 Opt 2
Fax: 01530 245786
HOT LINE: 01530 244444


VEHICLE	FLEET NO.	JOB/ADVICE NO.	INVOICE NO.	ORDER NO.	DATE	ACC NO.	VAN RUN
RDUCK	RDUCK	JC294826	77284634		12/06/26	H569	14




Wheel Position: B1 - Damage Size




Wheel Position: B1 - Completed Repair




Wheel Position: B1 - Torque 600.0 Nm



Wheel Position: B1 - Torque Wheel After




Wheel Position: B1 - Tread After



Wheel Position: B1 - Sidewall After



Wheel Position: B1 - Wheel Nut After



Wheel Position: B2 - Wheel Nut After



Mileage

INVOICE

VEHICLE	FLEET NO.	JOB/ADVICE NO.	INVOICE NO.	ORDER NO.	DATE	ACC NO.	VAN RUN
RDUCK	RDUCK	JC294826	77284634		12/06/26	H569	14



Vehicle Image - Post Work



Point of Work Risk Assessment (PoWRA)

Document Number: 77284634

Vehicle: RDUCK

Job Date: 12/06/26 12:46

Question

Answer

Have you got the relevant contact number in case of first aid treatment?

Yes

Have you carried out a final check of the work area for hazards?

Yes

Is there enough space to create a 3m Exclusion Zone and operate safely?

Yes

Are you wearing the appropriate PPE to carry out the work required?

Yes

Have you had the correct training required to complete the work safely?

Yes

Have you read and do you understand the Company's RAMS & SSOW?

Yes

Is there a risk from any of the following;

Yes

Is a site induction required?

Yes

Have you completed the site induction if necessary?

Yes

The following have been identified as risk items:

Tyrefix Plant Tyres (UK) Ltd
Spring Road
Ibstock
Leicestershire
LE67 6LR

Fax: 01530 245786

Accounts: 01530 244444 Opt3

HOT LINE: 01530 244444

Bank: SEB London Sort Code: 40-48-65
A/C Name: Tyrefix Plant Tyres (UK) Ltd
A/C Number: 65297005

INVOICE

BILLING ADDRESS

M.J.HICKEY (PLANT HIRE) LTD
10 WOOD LANE CLOSE
IVER HEATH
BUCKS

SL0 0LJ

VEHICLE

RDUCK

REG/FLEET NO.

RDUCK

SPEEDO/HRS

0

FITTING ADDRESS (IF DIFFERENT)

1X100020+DISP/WINCHE
Otterbourne
Thu/1x100020/winchester
Hampshire C/o Mgvj
SO21 2DT

CALLED IN

ON SITE

COMPLETED

VAN ID

254

FITTER

254 - JAY THOMPSON

ADVICE NO.

JC295797

INVOICE NO.

77284870

ORDER NO.


WILL

ACCOUNT NO.

H569

DATE

18/06/26



JOB CARD

Pos	Tyre Size	Tread Depths			Ply	PSI		Brand	Condition	Service able	Disposal	Comment
		Centre	Mid	Outer		BF	AF					
B4	10.00-20	15	20	26	16	10.0	100.0	ALLIANCE	New Tyre	Y	N	NEW TYRE
APPROVED by DH												

TYRES REMOVED

B4	10.00-20	12	15	22	16	0.0	SUMO	Very Poor	N	Y	Reason: Other. Damage Size: 25mm	
7883 - MGJV - Yew Hill Reservoir - 03/03/2026 - continues												
SIGNEE NAME: Not present							SITE CONDITION: Good					
SIGNED:												

INVOICE

DESCRIPTION	QTY	PRICE	VALUE
ALIANC 10.00-20 16PR 839 TT	1	491.00	491.00
DISPOSAL PLANT CASING 18-25"	1	35.00	35.00
CIB: WILL, 0787 9671 965			
Site Contact: MICHAEL, 07446 988887			
On Hire from: MJ HICKEY			
On Hire to: MG JV			
Customer portal advised ETA of: 18/06/2026			
1X 10.00/20 + DISPOSAL			
POS B4			
LOGGED FROM JC293948 PER WILL			
Vehicle Type: Rubber Duck			


RATE	AMOUNT TAXABLE	VAT TOTAL	TOTAL GOODS	TOTAL VAT	INVOICE TOTAL
20%	526.00	105.20	526.00	105.20	631.20

Tyrefix Plant Tyres (UK) Ltd
Spring Road
Ibstock
Leicestershire
LE67 6LR


INVOICE

Accounts: 01530 244444 Opt 2
Fax: 01530 245786
HOT LINE: 01530 244444

VEHICLE	FLEET NO.	JOB/ADVICE NO.	INVOICE NO.	ORDER NO.	DATE	ACC NO.	VAN RUN
RDUCK	RDUCK	JC295797	77284870	WILL	18/06/26	H569	14



Arrived on Site



Exclusion Zone




PPE



Vehicle Image - Reg/Fleet Num



Wheel Position: B4 - Tread Before



Wheel Position: B4 - Sidewall Before



Wheel Position: B4 - Wheel Nut Before



Wheel Position: B4 - Tread Depth Gauge



Wheel Position: B4 - Removed Damage Size

Tyrefix Plant Tyres (UK) Ltd
Spring Road
Ibstock
Leicestershire
LE67 6LR

Accounts: 01530 244444 Opt 2
Fax: 01530 245786
HOT LINE: 01530 244444

INVOICE

VEHICLE	FLEET NO.	JOB/ADVICE NO.	INVOICE NO.	ORDER NO.	DATE	ACC NO.	VAN RUN
RDUCK	RDUCK	JC295797	77284870	WILL	18/06/26	H569	14



Wheel Position: B4 - Tread Depth Gauge(Removed)



Wheel Position: B4 - Torque 600.0 Nm



Wheel Position: B4 - Torque Tag




Wheel Position: B4 - Torque Wheel After



Wheel Position: B4 - Tread After



Wheel Position: B4 - Sidewall After



Wheel Position: B4 - Wheel Nut After



Wheel Position: B4 - Torque Wheel Before



Vehicle Image - Post Work

Point of Work Risk Assessment (PoWRA)

Document Number: 77284870

Vehicle: RDUCK

Job Date: 18/06/26 13:13

Question

Answer

Is a site induction required?

No

Have you got the relevant contact number in case of first aid treatment?

Yes

Have you carried out a final check of the work area for hazards?

Yes

Is there enough space to create a 3m Exclusion Zone and operate safely?

Yes

Are you wearing the appropriate PPE to carry out the work required?

Yes

Have you had the correct training required to complete the work safely?

Yes

Have you read and do you understand the Company's RAMS & SSOW?

Yes

Is there a risk from any of the following;

Yes