



M.J. Hickey Plant Hire Ltd

Unit 11, Bristol Way Slough Berkshire SL1 3TD
T: 01753 651 202 E: enquiries@hickeyplanthire.co.uk W: www.hickeyplanthire.co.uk
VAT Reg. No. 480 0958 39

H248

PLANT PRE-DELIVERY INSPECTION SHEET PDI -

H+S ☒

RT ☒

FE ☒

ROTATE ☒

BIO OIL ☐

Make / Model	2x130-6	Date:	20/07/2026
Fleet Number	H248		
Hour Meter	3595 hrs		

Machine Serviced 250 ☐ 500 ☐ 1000 ☐ Service Computer reset ☐ Service sticker updated ☐

Service due 4075 hrs

Plant item	OK	Defect
------------	----	--------

Rams / bushings	✓	
-----------------	---	--

Cab Guards/Covers	N/A	
-------------------	-----	--

Lifting eye / points	✓	
----------------------	---	--

Cab glass	✓	
-----------	---	--

Chassis bolts & security	✓	
--------------------------	---	--

Seat secure & fully adjustable	✓	
--------------------------------	---	--

Tracks	✓	
--------	---	--

Blade / stabilizers if fitted	N/A	
-------------------------------	-----	--

Seat & Seat Belt	✓	
------------------	---	--

Steering if applicable	N/A	
------------------------	-----	--

Brakes as appropriate	N/A	
-----------------------	-----	--

Bodywork	✓	
----------	---	--

Operating Controls	✓	
--------------------	---	--

Warning Lights	✓	
----------------	---	--

Gauges/Instruments	✓	
--------------------	---	--

Railings / boxing ring	✓	
------------------------	---	--

Fan & other belts / chains	✓	
----------------------------	---	--

Fuel cap secured	✓	
------------------	---	--

Lenses & mirrors	✓	
------------------	---	--

Rear & 360° cameras	✓	
---------------------	---	--

Horn	✓	
------	---	--

Travel alarm	✓	
--------------	---	--

Lights / Beacons	✓	
------------------	---	--

Obvious Leaks	N/A	
---------------	-----	--

Safety pins & bolts	✓	
---------------------	---	--

Floor mats/ Air freshener	✓	
---------------------------	---	--

Fuel / Fluids	OK	Defect
Fuel Level	100%	
Fuel connectors & pipes	✓	
Engine Oil Level	100%	
Coolant Level	100%	
Hydraulic fluid level	100%	
Washer fluid level	100%	
Ad-blue level	N/A	
Refuelling Hose - present	✓	

Electric		
Cable Connections	✓	
General Cleanliness	✓	
Battery Security	✓	

Other Checks		
Front left wheels		
Front right wheels		
Rear left wheels		
Rear right wheels		

Defects / Service Details / Notes

ALL CHECKED OVER. ALL GREASED AND CLEANED AROUND. ALL IN WORKING ORDER.

Engineers name:

AC

Signature:

[Signature]