

|                         |                                 |                                |                |                  |                                                           |
|-------------------------|---------------------------------|--------------------------------|----------------|------------------|-----------------------------------------------------------|
| <b>Job No:</b>          | 56246                           | <b>Vehicle Reg / Fleet No:</b> | MV75BVL        | <b>Operator:</b> | MJ Hickey Plant Hire Ltd                                  |
| <b>Inspection Date:</b> | 22/07/2026                      | <b>Make / Model:</b>           | Scania / G540B | <b>Workshop:</b> | SGB Heathrow<br>Crane Road (off Bedfont Road)<br>TW19 ZLY |
| <b>Service Type:</b>    | Truck - Inspection Sheet<br>INS | <b>Chassis No:</b>             | 5778739        |                  |                                                           |
|                         |                                 | <b>Usage:</b>                  | 65072 Km       |                  |                                                           |

|                          |                                                         |                                                       |                                                                                                                       |
|--------------------------|---------------------------------------------------------|-------------------------------------------------------|-----------------------------------------------------------------------------------------------------------------------|
| <b>Planned ISO Week:</b> | 2026-W30                                                | <b>Actual ISO Week:</b>                               | 2026-W30                                                                                                              |
| <b>Judgement Key (J)</b> | <span style="color: green;">■</span> / ✓ = Satisfactory | <span style="color: yellow;">■</span> / M = Monitored | <span style="color: red;">■</span> / R = Requires attention <span style="color: gray;">■</span> / NA = Not applicable |

| IM                                                       | Check                                                                                                                                                                                                                                   | J  |
|----------------------------------------------------------|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|----|
| <b>Truck - Inspection Sheet:</b>                         |                                                                                                                                                                                                                                         |    |
| <b>Safety Pre check Electric Vehicle (HEV,PHEV,BEV):</b> |                                                                                                                                                                                                                                         |    |
| [0]                                                      | <span style="color: gray;">■</span> Complete Dynamic Risk assessment - Carry out assesment                                                                                                                                              | NA |
| [0]                                                      | <span style="color: gray;">■</span> Perform LOTO when working on Electric Vehicles- Lock Out Tag Out                                                                                                                                    | NA |
| <b>Safety Pre check Gas Vehicle (CNG,LNG):</b>           |                                                                                                                                                                                                                                         |    |
| [0]                                                      | <span style="color: gray;">■</span> Fuel system - check for leaks using appropriate tool. Shut off gas supply & run engine until stops                                                                                                  | NA |
| <b>Lubrication:</b>                                      |                                                                                                                                                                                                                                         |    |
| [0]                                                      | <span style="color: green;">■</span> Lubricate: Chassis & top up grease in the ACL reservoir.:                                                                                                                                          | ✓  |
| [0]                                                      | <span style="color: gray;">■</span> Manual gearbox - Check level is to the edge of level hole:                                                                                                                                          | ✓  |
| [0]                                                      | <span style="color: gray;">■</span> Automatic gearbox - Check level                                                                                                                                                                     | NA |
| [0]                                                      | <span style="color: green;">■</span> Axle gear: Check level:                                                                                                                                                                            | ✓  |
| [0]                                                      | <span style="color: gray;">■</span> Hydraulic Tag axle lift: Check oil level                                                                                                                                                            | NA |
| [0]                                                      | <span style="color: green;">■</span> Power steering: Check oil levels:                                                                                                                                                                  | ✓  |
| <b>In Cab:</b>                                           |                                                                                                                                                                                                                                         |    |
| [18]                                                     | <span style="color: green;">■</span> Seats: Check condition, operation & security.:                                                                                                                                                     | ✓  |
| [3]                                                      | <span style="color: green;">■</span> Seat belts & Supplementary Restraint Systems: Check condition & operation.:                                                                                                                        | ✓  |
| [16]                                                     | <span style="color: green;">■</span> Cab Doors & Windows: Check operation.:                                                                                                                                                             | ✓  |
| [23]                                                     | <span style="color: green;">■</span> Windscreen, glass and view of the road: Check condition.:                                                                                                                                          | ✓  |
| [0]                                                      | <span style="color: green;">■</span> FLC camera - visual check of bonding to windscreen:                                                                                                                                                | ✓  |
| [25]                                                     | <span style="color: green;">■</span> Windscreen washer/wiper: Check operation.:                                                                                                                                                         | ✓  |
| [22]                                                     | <span style="color: green;">■</span> Mirrors and Indirect Vision Devices, including camera-monitor systems: Check condition and Operation.:                                                                                             | ✓  |
| [30]                                                     | <span style="color: green;">■</span> Steering Control: Check operation and for play.:                                                                                                                                                   | ✓  |
| [34]                                                     | <span style="color: green;">■</span> Instruments & warning lamps: Check operation.:                                                                                                                                                     | ✓  |
| [33]                                                     | <span style="color: green;">■</span> Road Speed Limiter: Check operation, Check the set speed with SDP3, Check correct speed displayed on plaque: 90                                                                                    | ✓  |
| [26]                                                     | <span style="color: green;">■</span> Tachograph/Speedometer: Check operation & note calibration date.:                                                                                                                                  | ✓  |
| [27]                                                     | <span style="color: green;">■</span> Horn:                                                                                                                                                                                              | ✓  |
| [28]                                                     | <span style="color: green;">■</span> Driving Controls: Check operation:                                                                                                                                                                 | ✓  |
| [37]                                                     | <span style="color: green;">■</span> Service Brake Pedal: Check:                                                                                                                                                                        | ✓  |
| [34]                                                     | <span style="color: green;">■</span> Brake system: Check operating pressure, warning lamps, buzzer & for leaks.:                                                                                                                        | ✓  |
| [36]                                                     | <span style="color: green;">■</span> Electronic park brake control: Check for security, condition & operation, if applicable check hand lever (ratchet & pawl type) that operates mechanical brakes refer to IM for this type. :        | ✓  |
| [39]                                                     | <span style="color: gray;">■</span> Hand operated brake control valve: Check Operation                                                                                                                                                  | NA |
| [0]                                                      | <span style="color: green;">■</span> Park brake released audible warning: Check operation :                                                                                                                                             | ✓  |
| [0]                                                      | <span style="color: green;">■</span> Legal plate/VTG/Height indicator: Check details and condition.:                                                                                                                                    | ✓  |
| [0]                                                      | <span style="color: gray;">■</span> Cab Fire Extinguisher fitted.                                                                                                                                                                       | NA |
| [0]                                                      | <span style="color: gray;">■</span> Cab Fire Extinguisher next check date:                                                                                                                                                              | NA |
| <b>Action From Front And Side:</b>                       |                                                                                                                                                                                                                                         |    |
| [1]                                                      | <span style="color: green;">■</span> Number Plate: Check for legibility and security:                                                                                                                                                   | ✓  |
| [63]                                                     | <span style="color: red;">■</span> Lamps:                                                                                                                                                                                               | R  |
| [67]                                                     | <span style="color: green;">■</span> Aim of headlamps: Check horizontal, vertical alignment & pattern of headlamp beam using calibrated headlamp alignment equipment.:                                                                  | ✓  |
| [66]                                                     | <span style="color: green;">■</span> Direction indicators & hazard warning lamps:                                                                                                                                                       | ✓  |
| [62]                                                     | <span style="color: green;">■</span> Markers & reflectors and conspicuity Marking Tape (Refer to conspicuity marking requirements as per testers manual):                                                                               | ✓  |
| [9]                                                      | <span style="color: green;">■</span> Sideguards, Rear Under-Run Devices & bumper Bar: Check condition:                                                                                                                                  | ✓  |
| [0]                                                      | <span style="color: green;">■</span> DIS sensor visual inspection of mounting:                                                                                                                                                          | ✓  |
| [14]                                                     | <span style="color: green;">■</span> Spray Suppression, Wings and Wheel Arches: Check condition.:                                                                                                                                       | ✓  |
| [6]                                                      | <span style="color: green;">■</span> Road Wheels and Hubs: Check wheel nut security & damage to fixings: Check for wheel nut indicators (if applicable):                                                                                | ✓  |
| [7]                                                      | <span style="color: green;">■</span> Size, type and load index of Tyres:                                                                                                                                                                | ✓  |
| [8]                                                      | <span style="color: green;">■</span> Condition of tyres:                                                                                                                                                                                | ✓  |
| [8]                                                      | <span style="color: green;">■</span> Tyre aging: Check the date code on all tyres, check front steered tyres are not aged over 10 years old, check for legability, check date code is displayed. Report any defect as safety related. : | ✓  |
| [19]                                                     | <span style="color: green;">■</span> Bodywork: Security of Body, Containers and Crane Support Legs:                                                                                                                                     | ✓  |
| [20]                                                     | <span style="color: green;">■</span> Bodywork: Check Condition of body, check cab air deflector condition and security.:                                                                                                                | ✓  |
| [11]                                                     | <span style="color: gray;">■</span> Trailer coupling: Check condition & security. Confirm Lamp in Cab operational                                                                                                                       | NA |
| [12]                                                     | <span style="color: gray;">■</span> Trailer Parking and Emergency Brakes and Air line connections: Check condition, wear, damage.                                                                                                       | NA |
| [15]                                                     | <span style="color: green;">■</span> Cab: Check security of cab mountings, tilt mechanism, Catwalk, floor & steps.:                                                                                                                     | ✓  |
| [45]                                                     | <span style="color: green;">■</span> Fuel Tanks and System: Check Condition, Security and for Leakage. Ensure LNG safety valve caps are in place (if applicable), check Anti-siphon condition if fitted.:                               | ✓  |
| [5]                                                      | <span style="color: green;">■</span> Exhaust Emissions: check exhaust emissions meet the required criteria.:                                                                                                                            | ✓  |
| [46]                                                     | <span style="color: green;">■</span> Exhaust system, noise shields and noise encapsulation under cab, engine and gearbox : Check condition & security.:                                                                                 | ✓  |
| [59]                                                     | <span style="color: green;">■</span> Compressed air tanks: Check security & damage.:                                                                                                                                                    | ✓  |

| IM                                      | Check                                                                                                                                                                                                                                    | J  |
|-----------------------------------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|----|
| [42]                                    | <span style="color: green;">■</span> Batteries: Check electrolyte level/charge condition using midtronics/security. :                                                                                                                    | ✓  |
| [10]                                    | <span style="color: gray;">■</span> Spare wheel carrier: Check condition & security.                                                                                                                                                     | NA |
| [0]                                     | <span style="color: green;">■</span> Cooling system: Check fluid level & system condition, check and report antifreeze content using refractometer.:-38                                                                                  | ✓  |
| <b>Under The Vehicle:</b>               |                                                                                                                                                                                                                                          |    |
| [0]                                     | <span style="color: green;">■</span> Clutch operation: Check plate wear/fluid level/hose condition. :                                                                                                                                    | ✓  |
| [41]                                    | <span style="color: green;">■</span> Chassis frame & attachments: Check for cracks/loose bolts/rivets.:                                                                                                                                  | ✓  |
| [57]                                    | <span style="color: green;">■</span> Propeller shaft: Check condition/damage of driveshaft, U/J's & support bearing including PTO:                                                                                                       | ✓  |
| [43]                                    | <span style="color: green;">■</span> Engine & Transmission Mountings: Check condition.:                                                                                                                                                  | ✓  |
| [48]                                    | <span style="color: green;">■</span> Shock absorbers / Anti roll bars: check components for leaks and security:                                                                                                                          | ✓  |
| [48]                                    | <span style="color: green;">■</span> Spring leaves (air & leaf susp): Check clamps/pin/bushes.:                                                                                                                                          | ✓  |
| [48]                                    | <span style="color: gray;">■</span> Balance tandem: Check torque rods security/damage to mtg brackets.                                                                                                                                   | NA |
| [48]                                    | <span style="color: green;">■</span> Air suspension: Check for damage cones/air bags.:                                                                                                                                                   | ✓  |
| [48]                                    | <span style="color: green;">■</span> Tag axle/mid lift check opp.:                                                                                                                                                                       | ✓  |
| [48]                                    | <span style="color: gray;">■</span> Front air susp: Check torque rods security/damage to mounting brackets.                                                                                                                              | NA |
| [53]                                    | <span style="color: green;">■</span> Axles, Stub axles & wheel bearings: Jack up axles and rotate wheels, check condition of wheel bearings, stub axles and kingpins.:                                                                   | ✓  |
| [54]                                    | <span style="color: green;">■</span> Steering: Check PAS system & all joints & fixings. Rotate the steering wheel through its full working range, check steering components aren't obscured. Check condition of Hydraulic hoses & pipes: | ✓  |
| [59]                                    | <span style="color: green;">■</span> Brake system and components: Check condition of brake discs, drums and compressed air pipes: Check for damage to air lines/connectors/attachments.:                                                 | ✓  |
| [42]                                    | <span style="color: green;">■</span> Electrical Wiring and equipment. Care must be taken with high voltage cables (orange in colour) Check for additional damage to cables/connectors/attachments. :                                     | ✓  |
| [44]                                    | <span style="color: green;">■</span> Transmission Leakage including PTO:                                                                                                                                                                 | ✓  |
| [74]                                    | <span style="color: green;">■</span> Any other dangerous defects.:                                                                                                                                                                       | ✓  |
| <b>Engine Compartment (Cab Tilted):</b> |                                                                                                                                                                                                                                          |    |
| [0]                                     | <span style="color: green;">■</span> Engine: Check drive belt condition & tension. Have you carried out the approved belt tensioner check procedure inline with the Scania workshop manual. See notes section for work description: No   | ✓  |
| [0]                                     | <span style="color: green;">■</span> Compressor: Check security.:                                                                                                                                                                        | ✓  |
| [0]                                     | <span style="color: green;">■</span> Air filter: Check indicator.:                                                                                                                                                                       | ✓  |
| [44], [45], [46]                        | <span style="color: green;">■</span> Leakage: Start engine. Check for Oil/Coolant/Fuel/ Air/Exhaust Leaks.:                                                                                                                              | ✓  |
| <b>Brake System:</b>                    |                                                                                                                                                                                                                                          |    |
| [59]                                    | <span style="color: green;">■</span> Brake linings/Disc Pads: Check the thickness of the lining/Pads, record.:                                                                                                                           | ✓  |
| [59]                                    | <span style="color: gray;">■</span> Auto slack adjusters: Check basic settings.                                                                                                                                                          | NA |
| [59]                                    | <span style="color: gray;">■</span> Manual slack adjuster: Check & adjust stroke.                                                                                                                                                        | NA |
| [38]                                    | <span style="color: green;">■</span> Service Brake Operation: Check:                                                                                                                                                                     | ✓  |
| [71], [72], [73]                        | <span style="color: green;">■</span> Brake system: Test on a brake roller or with a decelerometer (record all readings):                                                                                                                 | ✓  |
| [58]                                    | <span style="color: green;">■</span> Additional Braking Devices: Check operation & condition of retarder & exhaust brake (or any additional braking device not specified):                                                               | ✓  |
| <b>Before Test Drive:</b>               |                                                                                                                                                                                                                                          |    |
| [0]                                     | <span style="color: gray;">■</span> Electrical control unit: Check, note & erase all fault codes in ECU                                                                                                                                  | NA |
| [0]                                     | <span style="color: gray;">■</span> Check and carry out ECU software updates                                                                                                                                                             | NA |
| <b>Road test:</b>                       |                                                                                                                                                                                                                                          |    |
| [28]                                    | <span style="color: gray;">■</span> Clutch and Gearbox: Check operation.                                                                                                                                                                 | NA |
| [0]                                     | <span style="color: gray;">■</span> Opticruise: Check operation.                                                                                                                                                                         | NA |
| <b>After Road Test:</b>                 |                                                                                                                                                                                                                                          |    |
| [0]                                     | <span style="color: gray;">■</span> Electrical Control Unit: Check, note & erase fault codes (send SVI to Operational analysis)                                                                                                          | NA |
| <b>Courtesy Item:</b>                   |                                                                                                                                                                                                                                          |    |
| [0]                                     | <span style="color: yellow;">■</span> Engine Oil: Check & top-up to the correct level.:                                                                                                                                                  | M  |
| [0]                                     | <span style="color: green;">■</span> Washer Fluid: Check & top-up washer fluid.:                                                                                                                                                         | ✓  |
| <b>Additional Items:</b>                |                                                                                                                                                                                                                                          |    |
| [26]                                    | <span style="color: green;">■</span> Tacho - Seals in place.: Yes                                                                                                                                                                        | ✓  |
| [26]                                    | <span style="color: green;">■</span> Tacho - K. Factor.: Yes                                                                                                                                                                             | ✓  |
| [0]                                     | <span style="color: green;">■</span> Clutch Disc thickness - record in MM or record % from ICL : 100%                                                                                                                                    | ✓  |
| [0]                                     | <span style="color: green;">■</span> Fire Extinguisher fitted External N/S                                                                                                                                                               | NA |
| [0]                                     | <span style="color: gray;">■</span> N/S Fire Extinguisher next check date:                                                                                                                                                               | NA |
| [0]                                     | <span style="color: gray;">■</span> Fire Extinguisher fitted External O/S                                                                                                                                                                | NA |
| [0]                                     | <span style="color: gray;">■</span> O/S Fire Extinguisher next check date:                                                                                                                                                               | NA |
| [0]                                     | <span style="color: gray;">■</span> Wheels Removed (If yes ensure wheel nuts retorque Label is placed in cab following refitting)                                                                                                        | NA |
| [0]                                     | <span style="color: gray;">■</span> Next Inspection Due Date:                                                                                                                                                                            | NA |
| [0]                                     | <span style="color: gray;">■</span> Smoke Alarm - Check operation                                                                                                                                                                        | NA |
| <b>Brake Performance:</b>               |                                                                                                                                                                                                                                          |    |
| [0]                                     | <span style="color: green;">■</span> Test / Evaluation Date: 22/07/2026                                                                                                                                                                  | ✓  |

|                         |                                 |                                |                |                  |                                                           |
|-------------------------|---------------------------------|--------------------------------|----------------|------------------|-----------------------------------------------------------|
| <b>Job No:</b>          | 56246                           | <b>Vehicle Reg / Fleet No:</b> | MV75BVL        | <b>Operator:</b> | MJ Hickey Plant Hire Ltd                                  |
| <b>Inspection Date:</b> | 22/07/2026                      | <b>Make / Model:</b>           | Scania / G540B | <b>Workshop:</b> | SGB Heathrow<br>Crane Road (off Bedfont Road)<br>TW19 ZLY |
| <b>Service Type:</b>    | Truck - Inspection Sheet<br>INS | <b>Chassis No:</b>             | 5778739        |                  |                                                           |
|                         |                                 | <b>Usage:</b>                  | 65072 Km       |                  |                                                           |

**Planned ISO Week:** 2026-W30 **Actual ISO Week:** 2026-W30

|                                    |                                     |                                                               |    |
|------------------------------------|-------------------------------------|---------------------------------------------------------------|----|
| [0]                                | <input checked="" type="checkbox"/> | Tested / Evaluated By (Technician's Name): J                  | ✓  |
| [0]                                | <input checked="" type="checkbox"/> | Test Method: Brake Rollers                                    | ✓  |
| [0]                                | <input checked="" type="checkbox"/> | Load Condition: Unladen                                       | ✓  |
| [0]                                | <input checked="" type="checkbox"/> | Performance Format: Percentage                                | ✓  |
| [71]                               | <input checked="" type="checkbox"/> | Service Performance: 41.00 Locked                             | ✓  |
| [72]                               | <input checked="" type="checkbox"/> | Secondary Performance: 25.00 Unlocked                         | ✓  |
| [73]                               | <input checked="" type="checkbox"/> | Parking Performance: 21.00 Unlocked                           | ✓  |
| [0]                                | <input type="checkbox"/>            | Do you need to log Tapley (Decelerometer) brake temperatures? | NA |
| <b>Speed Limiter Requirements:</b> |                                     |                                                               |    |
| [0]                                | <input checked="" type="checkbox"/> | Check road speed limiter performance:                         | ✓  |
| [33]                               | <input checked="" type="checkbox"/> | Road speed limiter (excludes speed check):                    | ✓  |
| <b>Tachograph Dates:</b>           |                                     |                                                               |    |
| [26]                               | <input checked="" type="checkbox"/> | Tachograph Type: Digital                                      | ✓  |
| [26]                               | <input checked="" type="checkbox"/> | Tachograph 2yr Expiry Date: 21/08/2027                        | ✓  |
| [26]                               | <input type="checkbox"/>            | Tachograph 6yr Expiry Date                                    | NA |

|                         |                                 |                                |                |                  |                                                           |
|-------------------------|---------------------------------|--------------------------------|----------------|------------------|-----------------------------------------------------------|
| <b>Job No:</b>          | 56246                           | <b>Vehicle Reg / Fleet No:</b> | MV75BVL        | <b>Operator:</b> | MJ Hickey Plant Hire Ltd                                  |
| <b>Inspection Date:</b> | 22/07/2026                      | <b>Make / Model:</b>           | Scania / G540B | <b>Workshop:</b> | SGB Heathrow<br>Crane Road (off Bedfont Road)<br>TW19 ZLY |
| <b>Service Type:</b>    | Truck - Inspection Sheet<br>INS | <b>Chassis No:</b>             | 5778739        |                  |                                                           |
|                         |                                 | <b>Usage:</b>                  | 65072 Km       |                  |                                                           |

**Planned ISO Week:** 2026-W30 **Actual ISO Week:** 2026-W30

**Note:** 0.0 = No check carried out.

| Nearside                                                                      |           |           |            |            | Offside    |            |            |           |   |
|-------------------------------------------------------------------------------|-----------|-----------|------------|------------|------------|------------|------------|-----------|---|
| Tyre pressure readings are as first inspected, any adjustments will be noted. |           |           |            |            |            |            |            |           |   |
| #                                                                             | Lining    |           | Depth:     | 7.00 mm    | Depth:     | 9.00 mm    |            | Lining    | # |
| 1                                                                             | 82 %      |           |            |            |            |            |            | 84 %      | 1 |
|                                                                               | Remaining |           | Pressure:  | 120.00 PSI | Pressure:  | 123.00 PSI |            | Remaining |   |
|                                                                               |           |           | Adjusted:  | N/A        | Adjusted:  | N/A        |            |           |   |
| #                                                                             | Lining    |           | Depth:     | 8.00 mm    | Depth:     | 10.00 mm   |            | Lining    | # |
| 2                                                                             | 82 %      |           |            |            |            |            |            | 79 %      | 2 |
|                                                                               | Remaining |           | Pressure:  | 128.00 PSI | Pressure:  | 124.00 PSI |            | Remaining |   |
|                                                                               |           |           | Adjusted:  | N/A        | Adjusted:  | N/A        |            |           |   |
| #                                                                             | Lining    | Depth:    | 13.00 mm   | Depth:     | 13.00 mm   | Depth:     | 13.00 mm   | Lining    | # |
| 3                                                                             | 82 %      |           |            |            |            |            |            | 81 %      | 3 |
|                                                                               | Remaining | Pressure: | 100.00 PSI | Pressure:  | 100.00 PSI | Pressure:  | 120.00 PSI | Remaining |   |
|                                                                               |           | Adjusted: | N/A        | Adjusted:  | N/A        | Adjusted:  | N/A        |           |   |
| #                                                                             | Lining    |           | Depth:     | 10.00 mm   | Depth:     | 10.00 mm   |            | Lining    | # |
| 4                                                                             | 86 %      |           |            |            |            |            |            | 86 %      | 4 |
|                                                                               | Remaining |           | Pressure:  | 110.00 PSI | Pressure:  | 108.00 PSI |            | Remaining |   |
|                                                                               |           |           | Adjusted:  | N/A        | Adjusted:  | N/A        |            |           |   |

| Brake Efficiency              |               |
|-------------------------------|---------------|
| Test Type                     | Brake Rollers |
| Brake Retardation - Service   | 41% L         |
| Brake Retardation - Secondary | 25%           |
| Brake Retardation - Park      | 21%           |

| TM                         | Defect                                                                                             | Authorised by                        | Actions            | Actioned by   |
|----------------------------|----------------------------------------------------------------------------------------------------|--------------------------------------|--------------------|---------------|
| Safety Related Defects     |                                                                                                    |                                      |                    |               |
| Non-Safety Related Defects |                                                                                                    |                                      |                    |               |
| 63                         | Custom Defect: Lamps: Reported Defect: osr outline marker not working                              | Fabrizio Formaggio (Self-Authorised) | Replaced: one bulb | Jason Creasey |
| Monitored Defects          |                                                                                                    |                                      |                    |               |
|                            | Custom Defect: Engine Oil: Check & top-up to the correct level.: Reported Defect: close to minimum | Fabrizio Formaggio (Self-Authorised) | Monitored          | Jason Creasey |

|                         |                          |                                |                |                  |                               |
|-------------------------|--------------------------|--------------------------------|----------------|------------------|-------------------------------|
| <b>Job No:</b>          | 56246                    | <b>Vehicle Reg / Fleet No:</b> | MV75BVL        | <b>Operator:</b> | MJ Hickey Plant Hire Ltd      |
| <b>Inspection Date:</b> | 22/07/2026               | <b>Make / Model:</b>           | Scania / G540B | <b>Workshop:</b> | SGB Heathrow                  |
| <b>Service Type:</b>    | Truck - Inspection Sheet | <b>Chassis No:</b>             | 5778739        |                  | Crane Road (off Bedfont Road) |
|                         | INS                      | <b>Usage:</b>                  | 65072 Km       |                  | TW19 ZLY                      |

|                          |          |                         |          |
|--------------------------|----------|-------------------------|----------|
| <b>Planned ISO Week:</b> | 2026-W30 | <b>Actual ISO Week:</b> | 2026-W30 |
|--------------------------|----------|-------------------------|----------|

|                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                   |                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                             |
|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| <p><b>Truck - Inspection Sheet</b></p> <div style="display: flex; align-items: center;">  <p>I/we declare that this vehicle has been inspected in accordance with current instructions and DVSA testers manual and all applicable items have been checked and found to be serviceable, except as noted.</p> </div> <div style="display: flex; justify-content: space-between; margin-top: 10px;"> <span><b>Name:</b> Jason Creasey</span> <span><b>Date:</b> 22/07/2026</span> </div> | <p><b>Foreman</b></p> <div style="display: flex; align-items: center;">  <p>All safety defects listed have been corrected and to the best of my knowledge and belief the vehicle has left this workshop in a safe and roadworthy condition.</p> </div> <div style="display: flex; justify-content: space-between; margin-top: 10px;"> <span><b>Name:</b> Fabrizio Formaggio</span> <span><b>Date:</b> 22/07/2026</span> </div> |
|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|