



Planned Date	23/05/2025 10:00	Distance reading	234	VIN	YV2RT60C6SB511267
Service Date	30/05/2025 21:10	Number of wheels	6x4	Model	FH (4)
Promised Date	02/06/2025 12:00	RegNo	AV25UYJ	Engine	D13K540
Order no.	1762616	Customer	Volvo T&B Ltd-new vehicle account	Address	Wedgnock Lane Warwick Warwickshire, CV34 5YA
				Make	Volvo

Brake Test

Brake Test

Judgement No Action Required General repair recommended Safety related **N/A** Not Applicable

Check No. IM No Judgement


CARRY OUT BRAKE TEST

1 Brake Test(71,72,73) 71,72,73

Roller brake test report attached

I have carried out, understood and analyzed the attached Roller Brake Test Report

Overall result: Passed



2 Inspectors comments(Mandatory if Failed) N/A



Planned Date	23/05/2025 10:00	Distance reading	234	VIN	YV2RT60C6SB511267
Service Date	30/05/2025 21:10	Number of wheels	6x4	Model	FH (4)
Promised Date	02/06/2025 12:00	RegNo	AV25UYJ	Engine	D13K540
Order no.	1762616	Customer	Volvo T&B Ltd-new vehicle account	Address	Wedgnock Lane Warwick Warwickshire, CV34 5YA
				Make	Volvo

Declarations

Technician Declaration

I can confirm that I am technically qualified to complete the above inspection, tests and/or calibrations.
The above items have been inspected in accordance with the UK or the ROI testers manuals.

Declaration made by Jeffrey Coldwell, 31/05/2025 06:51

Supervisor Declaration

NO OUTSTANDING SAFETY DEFECTS

The vehicle has been inspected and where identified and listed, all safety defects have been rectified, and the vehicle is now in a safe, legal, and roadworthy condition.

Declaration made by Edward Ferguson, 03/06/2025 12:52

NOTE: IT IS ALWAYS THE RESPONSIBILITY OF THE OPERATOR TO ENSURE THAT THE VEHICLE OR TRAILER IS IN A ROADWORTHY CONDITION BEFORE BEING USED ON THE ROAD.



Planned Date	23/05/2025 10:00	Distance reading	234	VIN	YV2RT60C6SB511267
Service Date	30/05/2025 21:10	Number of wheels	6x4	Model	FH (4)
Promised Date	02/06/2025 12:00	RegNo	AV25UYJ	Engine	D13K540
Order no.	1762616	Customer	Volvo T&B Ltd-new vehicle account	Address	Wedgnock Lane Warwick Warwickshire, CV34 5YA
				Make	Volvo

Pre Delivery Inspection

Pre Delivery Inspection

Judgement ✓ No Action Required ⚠ General repair recommended ⚠ Safety related **N/A** Not Applicable

Check No.	IM No	Judgement
Battery Information and Checks		
1		✓
Test batteries, Put Batteries on charge, Re-test batteries and print out Test Results. Record results, in Check 1,2 and 3		
2		N/A
Check 1 - Before Delivery to Body Builder – (From Battery Report Card delivered with Truck)		
3		
Check 2 - On return from Body Builder		
SOH 100% SOC 95%		
4		N/A
Check 3 - Before Customer Collection/Handover or PDI.		

Check No.	IM No	Judgement
Inside Cab Checks		
5		
Take photo of Tacho & Dash to show mileage, any warnings and oil level PRIOR to Inspection		
Dash		
		
6		✓
All Safety Campaigns have been carried out		
7		✓
All Non Safety Campaigns have been carried out		
8		✓
Carry out Complete Vehicle Software Update (CVSU) using Workshop Toolbox.. FH/FM SERVIN-B ONLY		
9		✓
Carry Out Operation 36662-3, Key Counting.		
10	5	✓
Exhaust Emissions OBD/MIL Light		
11		✓
Check, Review all DT Codes and Erase		
12	25	✓
Wscreen Wipers and Washers		
13	1	✓
Registration Plate and Legal Plates		
14	42	✓
Electronic Wiring & Equipment		
15	42	✓
Lighting & Equipment (Switches) Instrument Illumination		
16	27	✓
Audible Warning (Horn) Including Reverse Alarm		
17	26	✓
Speedometer/Tachograph..Function & Condition		
18	26	✓
Tachograph...Spare Tachograph Roll/s are available. Minimum of 2 Rolls.		



Planned Date	23/05/2025 10:00	Distance reading	234	VIN	YV2RT60C6SB511267
Service Date	30/05/2025 21:10	Number of wheels	6x4	Model	FH (4)
Promised Date	02/06/2025 12:00	RegNo	AV25UYJ	Engine	D13K540
Order no.	1762616	Customer	Volvo T&B Ltd-new vehicle account	Address	Wedgnock Lane Warwick Warwickshire, CV34 5YA
				Make	Volvo

19	Smoke Alarm(Detector) Operation		✓
20	Seat & Seat Belts & Supplementary restraint System	18/3	✓
21	Mirrors & Indirect Vision Devices	22	✓
22	Glass & View of the Road	23	✓
23	Activate vehicle electrical system (PDI 12)		✓
24	Run accessory kit 85149063 for Park Mode / Fridge Timer function		✓
25	Activate the work remote control (PDI 13)	N/A	
26	Activate alcolock (PDI 14)	N/A	
27	Activate radio (PDI 15)		✓
28	Activate anti-theft alarm (PDI 16)	N/A	
29	Warning and control symbols (PDI 17)		✓
30	Function check of parking heater (PDI 18)		✓
31	Function check of integrated parking heater (PDI 19)	N/A	
32	Run Telematics System SIM ID (39733-3) to secure correct data in central systems		✓
33	Run Telematics Connectivity, Check and Activation (39824-3)		✓
34	Check cab power outlets		✓

Check No. IM No Judgement

Driver Controls			
35	Driving Controls	28	✓
36	Hand Levers Operating Mechanical Brakes	36	✓
37	Hand-Operated Brake Control Valves	39	✓
38	Check Handbrake warning with all door operations		✓
39	Additional Braking Device	58	✓
40	Pressure/Vacuum Warning and Build Up	34	✓
41	Steering Control	30	✓
42	Service Brake ABS/EBS Warning	38	✓
43	Clutch/Brake Pedal Carrier & Pads	28/37	✓
44	Cab Floor & Steps	17	✓
45	Speed Limiter	33	✓

Check No. IM No Judgement

Cab Exterior			
46	Cab Doors	16	✓
47	Cab lubrication incl. door locks / catches – follow IMPACT document 131795213		✓

Volvo Truck and Bus Centre - South & East (E)



Planned Date	23/05/2025 10:00	Distance reading	234	VIN	YV2RT60C6SB511267
Service Date	30/05/2025 21:10	Number of wheels	6x4	Model	FH (4)
Promised Date	02/06/2025 12:00	RegNo	AV25UYJ	Engine	D13K540
Order no.	1762616	Customer	Volvo T&B Ltd-new vehicle account	Address	Wedgnock Lane Warwick Warwickshire, CV34 5YA
				Make	Volvo

48	Cab & Body Including Ventilation	15/19/20	✓
49	Cab Security/ Mounting & Tilt Mechanism (Tilt the cab)	15	✓

Check No.		IM No	Judgement
Lights & Reflectors			
50	Lamps (ALL)	63	✓
51	Direction Indicators & Hazard Warning	66	✓
52	Headlamps & Aim	67	✓
53	Rear Markers and Reflectors	62	✓

Check No.		IM No	Judgement
Ground Level			
54	Condition, Attachment & Security of Body/Superstructure, Incl.Ladders, Folding Steps, etc...	19/20	✓
55	Security & Condition of Body	19/20	✓
56	Other dangerous defects	74	✓
57	Sideguards, Rear Under-Run Devices and Bumper Bars	9	✓
58	Road Wheels and Hubs, Spare Wheel and Carrier	6/10	✓
59	Wheels (dimensions and paintwork) - Check		✓
60	Attach wheel nut protection (PDI 24)		✓
61	Wheel Nuts torque tighten check.	6	✓
62	Remove and Re-fit wheel nut security system (if applicable)		✓
63	Wheel Nuts Re-Torqued After Wheel Removal	6	N/A
64	Wheels Removed Warning Label Placed In Cab	6	N/A
65	Tyres (inc. Size, Type and Condition)	7/8	✓
66	Spray suppresssion, wings and wheel arches	14	⚠
67	Trailer Coupling inc. Drawbar/Fifthwheel and Lubricate trailer air couplings..... lubricate and top up grease systems where applicable .	11	✓
68	Air Tanks (Drain & Check)		✓
69	Fuel Tanks & System	45	✓
70	Trailer Parking , Emergency Brakes and Air Line Connections	12	✓

Check No.		IM No	Judgement
Ground Level & Under Vehicle			
71	Engine and Transmission Mountings	43	✓
72	Oil Leaks	44	✓
73	Cooling System, Security and Leaks		✓
74	EGR Cooler Coolant hose clamps check for tightness (D8K ONLY)		N/A

Volvo Truck and Bus Centre - South & East (E)



Planned Date	23/05/2025 10:00	Distance reading	234	VIN	YV2RT60C6SB511267
Service Date	30/05/2025 21:10	Number of wheels	6x4	Model	FH (4)
Promised Date	02/06/2025 12:00	RegNo	AV25UYJ	Engine	D13K540
Order no.	1762616	Customer	Volvo T&B Ltd-new vehicle account	Address	Wedgnock Lane Warwick Warwickshire, CV34 5YA
				Make	Volvo

75	Exhaust Systems & Nuisance	46	✓
76	Attach tail pipe		✓
77	Exhaust Emissions.	5	✓
78	Attach cab emblems		N/A
79	Replace battery transit cable (PDI 7)		N/A
80	Cab and chassis / body - Check		✓
81	Over Length and width of vehicle		⚠

Check No. IM No Judgement

Under Vehicle & Cab			
82	Condition of Chassis	41	✓
83	Traction voltage system, REF Impact Main Service(17710).		N/A
84	Follow and action where required TPI 17 177 for FLE & FEE only !		N/A
85	Electrical Wiring and Equipment	42	✓
86	Starter Motor Link Cable, Clean Check and Protect . TPI 17 170		✓
87	Drive Belts, Condition and Security		✓
88	Transmission U/Joints, Slider & Centre Bearings	57	✓
89	Suspension	48	⚠
90	Axles, Stub Axles and Wheel Bearings	53	✓
91	Steering	54	✓
92	Tacho Seal (incl G/Box drive)	26	✓
93	Brake System and Components	59	✓
94	Load Sensing Valve Setting- Check VTT Op 72204-3 (PDI 31)		N/A
95	Calibration Axle Load Sensor- Check VTT Op 72204-3 (PDI 32)		N/A

Check No. IM No Judgement

Fluids & Lubrication			
96	Windscreen/headlamp washers - Check / Top up. (PDI 2)		✓
97	Battery, charging and fluid level - Check / Top up. (PDI 6)		N/A
98	Coolant -Check/Top Up Level and Check Specific Gravity		⚠
99	Check Engine Oil level and top up to Max. according to dash (PDI 4)		✓
100	Gearbox oil level - Check / Top up		✓
101	Rear axle oil level - Check / Top up.. Ref to Impact 17561-3		✓
102	Hub / hub reduction oil level - Check / Top up.. Ref to Impact 17561-3		N/A
103	Ad-Blue tank level - Check / Top up. (PDI 5)		✓

Volvo Truck and Bus Centre - South & East (E)



Planned Date	23/05/2025 10:00	Distance reading	234	VIN	YV2RT60C6SB511267
Service Date	30/05/2025 21:10	Number of wheels	6x4	Model	FH (4)
Promised Date	02/06/2025 12:00	RegNo	AV25UYJ	Engine	D13K540
Order no.	1762616	Customer	Volvo T&B Ltd-new vehicle account	Address	Wedgnoek Lane Warwick Warwickshire, CV34 5YA
				Make	Volvo

104	Grease Spring Pins & Bushes (Where fitted on 8*4)	N/A
105	Trailer Coupling Lubrication	✓

Check No. IM No Judgement

Test Drive Checks

106	Checks after starting (PDI 35)	✓
107	Checks during test drive (PDI 36)	✓
108	Checks after test drive (PDI 37)	✓

Check No. IM No Judgement

Miscellaneous

109	Remove protective covers (PDI 39)	✓
------------	--	---

Check No. IM No Judgement


LNG

110	Calibrate LNG tank prior to commissioning	N/A
111	LNG Commissioning Completed	N/A

Check No. IM No Judgement

Data Input Section

112	Tyre Depths and Record (7/8)	7/8
------------	-------------------------------------	------------






Planned Date	23/05/2025 10:00	Distance reading	234	VIN	YV2RT60C6SB511267
Service Date	30/05/2025 21:10	Number of wheels	6x4	Model	FH (4)
Promised Date	02/06/2025 12:00	RegNo	AV25UYJ	Engine	D13K540
Order no.	1762616	Customer	Volvo T&B Ltd-new vehicle account	Address	Wedgnock Lane Warwick Warwickshire, CV34 5YA
				Make	Volvo


113 Measured Tyre Pressures in PSI. (7/8)

7/8



114 Inflated Tyre Pressures in PSI. (7/8)


7/8



115 Check Tyre Pressure Monitoring Calibration" (especially after tyre pressure adjustment)



116 Remaining Brake Pad/Shoe Lining Thickness (% or MM) (59)



117 Brake Lever Travel (59)

N/A

118 Clutch Wear (Clutch 1)

X1	X2	X1-X2	Service Due Position
18.9 mm	18.9 mm	0 mm	9.1 mm

119 Clutch Wear (Clutch 2 if fitted)

N/A

120 Mid Tronic Battery Test Results

N/A

Volvo Truck and Bus Centre - South & East (E)



Planned Date	23/05/2025 10:00	Distance reading	234	VIN	YV2RT60C6SB511267
Service Date	30/05/2025 21:10	Number of wheels	6x4	Model	FH (4)
Promised Date	02/06/2025 12:00	RegNo	AV25UYJ	Engine	D13K540
Order no.	1762616	Customer	Volvo T&B Ltd-new vehicle account	Address	Wedgnock Lane Warwick Warwickshire, CV34 5YA
				Make	Volvo

121 Road Speed Limiter (33) 33

Road speed limiter set to:: 90 UNIT.KMH

Speed recorded on label:: 90 UNIT.KMH

Road speed limiter exempt:: ☐

122 Tachograph (26) 26

Tacho Type	Mileage	Tacho Calibration Expiry Date
DigitalTacho	234 UNIT.KM	31/05/2027

Check No. IM No Judgement

Miscellaneous

123 Take photo of Tacho & Dash to show mileage, any warnings and oil level FOLLOWING Inspection

Dash 2





Planned Date	23/05/2025 10:00	Distance reading	234	VIN	YV2RT60C6SB511267
Service Date	30/05/2025 21:10	Number of wheels	6x4	Model	FH (4)
Promised Date	02/06/2025 12:00	RegNo	AV25UYJ	Engine	D13K540
Order no.	1762616	Customer	Volvo T&B Ltd-new vehicle account	Address	Wedgnoek Lane Warwick Warwickshire, CV34 5YA
				Make	Volvo

Defect Report

- ✓ Repaired
✗ Outstanding

Check No.	Defect	IM No	Repair code	Repaired by
-----------	--------	-------	-------------	-------------

General Related Defects

66	Description Rear wing tops misshaped Repair Description	14	✗	
	  			
81	Description W=2500m L=6670mm Repair Description		✗	
89	Description Pipe chafing cross member rear Repair Description Reposition	48	✓	Jeffrey Coldwell 31/05/2025
				
98	Description Level high Repair Description Drain to level		✓	Jeffrey Coldwell 31/05/2025
				

Norwich	Phone	Date/Time	Assisted By	Page No.
24-28 Frensham Road, Sweet Briar Ind. Estate, Norwich, NR3 01603 785100 2BT		03/06/2025 12:52	Edward Ferguson	10 / 11



Planned Date	23/05/2025 10:00	Distance reading	234	VIN	YV2RT60C6SB511267
Service Date	30/05/2025 21:10	Number of wheels	6x4	Model	FH (4)
Promised Date	02/06/2025 12:00	RegNo	AV25UYJ	Engine	D13K540
Order no.	1762616	Customer	Volvo T&B Ltd-new vehicle account	Address	Wedgnock Lane Warwick Warwickshire, CV34 5YA
				Make	Volvo

Declarations

Technician Declaration

I can confirm that I am technically qualified to complete the above inspection, tests and/or calibrations.
The above items have been inspected in accordance with the UK or the ROI testers manuals.

Declaration made by Luke Petley, 02/06/2025 11:28

Supervisor Declaration

NO OUTSTANDING SAFETY DEFECTS

The vehicle has been inspected and where identified and listed, all safety defects have been rectified, and the vehicle is now in a safe, legal, and roadworthy condition.

Declaration made by Edward Ferguson, 03/06/2025 12:52

NOTE: IT IS ALWAYS THE RESPONSIBILITY OF THE OPERATOR TO ENSURE THAT THE VEHICLE OR TRAILER IS IN A ROADWORTHY CONDITION BEFORE BEING USED ON THE ROAD.